

Annexure D

BUILDING SAFETY CERTIFICATE

No 72/2024Dated 22/4/2024

It is certified that the existing building Shinde International School (name of the building or premises) at Bambrud Kh. Taluka Pachora, District Jalgaon (address) is having block(s)/Floor(s) as per details below

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No of Floor(s) in the Block	3	NIL	NIL	NIL	NIL	NIL

The building is owned/occupied by **SHINDE INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD** (Name of Department / Govt.) on 19/4/2024 (date of inspection) in the presence of **MR. PANDITRAO PARSHRAM SHINDE** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 19/4/2024 for a period of 2 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NIL
2. NIL
3. NIL
4. NIL

Issued on 22/4/2024 at 11.00 am by

Strike out whichever is not applicable in case of block is more than six use separate sheet for detail

Signature with Seal : 
Deputy Engineer
P.W. Sub Dn., Pachora

Name : D. M. Paril

Designation : Sub. Divisional Engineer

Name & Address of Department/ Office: P. W. Sub. Div.

Pachora.